


### Lens Markings & Centration Chart



### Lens Material Types

CR 39, Transitions, Polarized, Divewear

Poly, Transitions, Polarized

Trivex, Transitions, Polarized

1.60, Transitions, Polarized

1.67, Transitions, Polarized

1.74

### Solidar Express Coatings, LLC

Toll Free (855) 272-6284


Local (727) 585-2192

Fax (727) 585-2318

12912 91st Street N, Largo, FL 33773

[www.SolidarExpressCoatings.com](http://www.SolidarExpressCoatings.com)

## Frame Wrap Chart



**solidar**  
OPTICAL LABORATORY

### Lens Material Types

CR 39, Transitions, Polarized, Divewear

Poly, Transitions, Polarized

Trivex, Transitions, Polarized

1.60, Transitions, Polarized

1.67, Transitions, Polarized

1.74

### Solidar Express Coatings, LLC

Toll Free (855) 272-6284

Local (727) 585-2192

Fax (727) 585-2318

12912 91st Street N, Largo, FL 33773

[www.SolidarExpressCoatings.com](http://www.SolidarExpressCoatings.com)